

Armouring with Plastic Protection Hood

A 325/K



Assembly


1. Push sensor 4 through the armouring 3.



A 325/K

Assembly / Technical data

2. Put clamping ring **1** on the connection cable **2**.



The side with the sharp-edged notch must show to the armouring head!

- 3. Squeeze clamping ring **1**, put it into the armouring **3** and make it catch.
- 4. Push sensor 4 into the armouring 3 as far as possible.
- 5. Screw sensor 4 with fixing nut 5 into the armouring 3 by hand.
- 6. Screw on protection hood 6.

Technical data

Type Armouring with plastic protection hood

Suitable for sensors TetraCon 325® up to 20 m cable length

CellOx 325® up to 20 m cable length

Material Armouring POM Distributed by:

Protection hood POM Clamping ring POM

Diameter 38 mm

Total length 192 mm

distributed by:



ADVANCED APPLIED TECHNOLOGIE

Contact Us: Irl Ph: 01 4523432

UK Ph: 08452 30 40 30 Web: www.carlstuart.com Email: info@carlstuart.com